

FIG. 2




FIG. 3

+




FIG. 4




FIG. 8

6 - RECOVERED 5 - NORMAL OPERATION 4 - WAITING FOR START 2 - WAITING FOR 3 - READY FOR RESET 1 - TRIPPED STATES 7 - START RECOVER 6- TRIP REQUESTED 4 - START PERMIT 2 - RESET PERMIT 5 - NORMAL 1 - INITIAL INPUTS 3- RESET

FIG. 5


304



			\	300		
			304B /			
STATES	1 - TRIPPED	2 - WAITING FOR RESET	3 - READY FOR RESET	4 - WAITING FOR START	5 - NORMAL OPERATION	6 - RECOVERED
- INITIAL	2 - WAITING FOR RESET	- 304A	2 - WAITING FOR RESET			
2 - RESET PERMIT	3 - READY FOR RESET	3 - READY FOR ♦ RESET				
3- RESET	4 - WAITINF FOR START		4 - WAITINF FOR START			
4 - START PERMIT				5 - NORMAL OPERATION		
5 - NORMAL	5 - NORMAL OPERATION		5 - NORMAL OPERATION			
5- TRIP REQUESTED		1 - TRIPPED ∳	1 - TRIPPED	1 - TRIPPED	1 - TRIPPED	1 - TRIPPED
7 - START RECOVER	×				6 - RECOVERED	
	304D	1 304C				

9 <u>9</u> 9

MARSHALL, GERSTEIN & BORUN LLP (312-474-6300)






FIG. 9




FIG. 10






FIG. 11





_ 1





FIG. 14






FIG. 16

END




FIG. 17